

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:								
Company	Dennis Oakley							
OGM	Steve Demczak							

Inspection Report

Permit Number:	C0150017		
Inspection Type:	PARTIAL		
Inspection Date:	Monday, July 12, 2010		
Start Date/Time:	7/12/2010 10:00:00 AM		
End Date/Time:	7/12/2010 1:00:00 PM		
Last Inspection:	Monday, June 14, 2010		

Inspector: Steve Demczak,

Weather: Sunny, 90's

InspectionID Report Number: 2424

Accepted by: jhelfric

7/29/2010

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: DES BEE DOVE MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	134.31
Total Disturbed	40.90
Phase I	43.40
Phase II	
Phase III	2.52

Mineral Ownership Types of Operations

✓ Federal ✓ Underground

☐ State ☐ Surface

 □ County
 □ Loadout

 ✔ Fee
 □ Processing

 □ Other
 □ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violation were issued.

Inspector's Signature:

Steve Demozak,

Date

Monday, July 19, 2010

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Monday, July 12, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	<u> </u>		✓	
2.	Signs and Markers				
3.	Topsoil	✓		~	
4.a	Hydrologic Balance: Diversions	V		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		✓		
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	V		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	✓		✓	
13.	Revegetation	V		V	
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.t	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		V	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Monday, July 12, 2010

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

There is no pending permitting action with the Division at this time. The identification signs is located on the trail to the mine site.

3. Topsoil

All topsoil was used in reclamation.

4.a Hydrologic Balance: Diversions

Diversions were spot-checked and would function in a storm event. There were no signs of water erosion to the diversion.

4.c Hydrologic Balance: Other Sediment Control Measures

The mine site is pocked to control sediment control.

8. Noncoal Waste

The area was clear of non-coal waste material.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

12. Backfilling And Grading

The site is backfilled and graded.

13. Revegetation

Vegetation is coming up throughout the property.

18. Support Facilities, Utility Installations

There are no facilities at this site.